Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	53844	((load force weight stress strain) near2 (test\$5 detect\$5 sens\$5 estimat\$5 identif\$6 evaluat\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:40
L2	457	1 and notches.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:41
L3	43	2 and (curv\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:41
L5	3	3 and (strain near2 gauge).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:42
L6	56	2 and (strain near2 gauge).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:42
L7	51	6 and (connect\$5 coupl\$5 attach\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/04/06 08:43